

Scientifics Group Services Ltd
SGS House
Johns Lane
Tividale
Oldbury
West Midlands
B89 3HX
Tel: (0121) 557 0844
Fax: (0121) 520 6530

CHARTERBRAE LIMITED
Coneygre Industrial Estate
Tipton
West Midlands
DY4 8XP

TEST REPORT No. ESD 47352/00-01A

This report supersedes all previous documents bearing the reference ESD 47352/00-01.

Date: 9th August 2001

Page: 1 of 1

Your Ref: 15304

DATE RECEIVED: 25th October 2000

Loading to Failure of a Warwick Bed with 3 cross supports, and Flat weld skid legs.

INTRODUCTION

The Product Testing Department of Scientifics Group Services were asked to perform load testing to Warwick steel bed.

METHOD

The loads were applied by using dead weights, starting from the centre outwards to evenly spread the load.

RESULTS


The bed frame yielded at a load of 900 kgs, final failure occurred at a load of 1238 kg by the legs collapsing.

After inspection of a Windsor bed it is our opinion that the only difference is that the Windsor bed as a square end for fitting head board, compared to a Warwick bed and this does not affect the strength of the bed.

Tested By: J. Power, Technician

Test Date: 27th October 2000

Authorised By:



D. Skeldon, Testing Supervisor

Enquiries relating to the content of this report to be directed to the above-authorised signatory.